



February 27th, 2026

Week 8 Update – Turf Construction at Spectrum



Photo by Spectrum student: Sawyer Stevens

Construction crews are continuing to complete the drainage work around the new field. Electrical service work has now begun, which has expanded the worksite footprint. Safety fencing has been installed around the newly affected area.

Ongoing site safety measures will remain in place, including maintenance of silt fencing for sediment control and snow fencing to define the work zone. Tree protection fencing will continue to be monitored and maintained as required. We like to remind our community to be cautious around the construction site and to be aware of construction traffic accessing the site at the Marigold/West Burnside Road intersection.

If you have any questions, please reach out to any of the Admin Team.

Aaron Norris, Christina Pelletier and Phil Ohl